

Building Safety Certificate

Part - 1

Performa For The Safety School Building
(To be filled by the Head of School / Institute)

1. Name of School S.D.P. College for Women, S.D.P. collegiate Girl Sr.
2. Location Behind fort, Daresi Road, Ludhiana. Sec. School.
3. Plot Area 6.704 Acres
4. Plinth Area 48384 Sqft (GF) + 30700 Sqft (1st floor) = 79084 sqft
5. Number of Storey One
6. Year of Construction of building 1967-1968
7. Supervision of the qualified Engineer,
The following details may be given:
 - a) Name of the Engineer Er. Harbans Singh Sekhon
 - b) Address No. 4-A, Sargodha Colony, Pakhowal Road, Ludhiana.
 - c) Set of Structure Drawing used in the construction if available
 - d) Name of the Architect Sekhon Associates
8. Whether the building has been constructed for the purpose of :
 - a) School (Yes / No) Yes
 - b) Residential purpose and converted for use as a school (Yes / No) No
9. Materials used for Roof:
 - a) R.C.C. slabs (Yes / No) Yes
 - b) R.S. Joists and Battens (Yes / No) Yes
 - c) Wooden Joists and Battens (Yes / No) No
10. Materials used for walls:
 - a) Mud Mortar (Yes / No) No
 - b) Cement Mortar (Yes / No) No
 - c) Plaster (i) Lime Mortar (Yes / No) No
(ii) Cement Mortar (Yes / No) Yes
11. Flooring :
 - a) Conglomerate (Yes / No) -
 - b) Terrazzo (Yes / No) -
 - c) Brick Paving (Yes / No) Yes
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows Attached

Principal,

S.D.P. College for Women,

Signature LUDHIANA-141008

The Head of the School / Institute

Part-II
(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 6/8/25 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.


In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.


The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 21/3/26 (indicate year up to which it can be used).


Sub Divisional Engineer

Sub Divisional Engineer,
Provincial Sub Division No. 3,
P.W.D. B&R, Br. LUDHIANA.


Principal,
S.D.P. College for Women,
LUDHIANA-141008